Icon overview

Incontinence monitoring



No urine | Little | Medium | A lot | Full

Under development:



No stool | Stool detected

Fall detection



Suspected fall

Safe Zone



Left Safe Zone

Body position detection



Example:



Movement to the right (ca. 30°) | Repositioning interval reached

TZMO Deutschland GmbH, Waldstraße 2, 16359 Biesenthal | seni-smart@tzmo.de

AssistMe GmbH | Bachstr. 12, 10555 Berlin | support@assistme.io

Icon overview

System events

Faulty clip connection

No clip connected to ICP

Clip not properly attached

2 clips in use at the same time

Clip probably disposed

Clip needs charging

Clip battery empty

No data connection



From icon to action

TZMO Deutschland GmbH, Waldstraße 2, 16359 Biesenthal | seni-smart@tzmo.de

AssistMe GmbH | Bachstr. 12, 10555 Berlin | support@assistme.io